



FIRMWARE HISTORY

Evolis is conducting for many years a general policy to improve the quality and features of his printer range.

This document describes modifications and improvements from original firmware release to the latest available from Evolis website version 2212 released on April 2022.

Related printers' models:

Badgy 100

Badgy 200

Summary

Firmware version – 2212 (A293)	3
Firmware version – 2126 (74CD)	3
Firmware version – 1759 (2996)	3
Firmware version – 1757 (534F)	3
Firmware version – 1754 (CB62).....	3
Firmware version – 1634 (9C62)	3
Firmware version – 1631	3
Firmware version – 1626	4
Firmware version – 1624	4
Firmware version – 1605.....	4
Firmware version – 1504.....	4
Firmware version – 1443.....	4
Firmware version – 1426.....	4

Version History

11/04/2022

Firmware version – 2212 (A293)

- BlackFlex ribbon printing process improvement.
- YMCKO ribbon synchronisation improvement.
- Add sensor color adjustment in the automatic process at printer power ON, or printer wake up after standby or sleep mode and before printing job.
- Bug fix on backup ribbon position before shutdown.

21/10/2021

Firmware version – 2126 (74CD)

- New configurable auto-sensor adjustment. Card Sensor auto-adjustment is performed automatically at printer power ON, or printer wake up after standby or sleep mode and before printing job. New Escape command 'Aase' to enable/disable sensors auto-adjustment.
- Add new BlackFlex ribbon management compatible with eco-friendly paper cards.

09/08/2021

Firmware version – 1759 (2996)

- Cam sensor detection improved.

04/12/2020

Firmware version – 1757 (534F)

- Firmware version alignment.

13/05/2020

Firmware version – 1754 (CB62)

- Cleaning warning management (Pcsc / Rcsc added commands)
- Power supply voltage control (when power on printer)
- Ribbon management improvement (enable/disable ribbon synchronization when power on or exit from standby mode)
- Color (YMC) panel's contrasts improvement.

04/07/2017

Firmware version – 1634 (9C62)

- Ribbon management improvement.

16/12/2016

Firmware version – 1631

- Pre-heating mode improvement.
- Internal memory data backup improvement.

06/09/2016

Firmware version – 1626

- Varnish quality improvement.

06/07/2016

Firmware version – 1624

- Print head temperature regulation improvement.
- Print head signal management improvement.

18/02/2016

Firmware version – 1605

- Color sensor adjustment process improvement.
- USB communication improvement.
- Technical test card printing process improvement.
- Add monochrome speed management.

02/02/2015

Firmware version – 1504

- Sleep mode disable by default.
- USB device communication improvement (USB Certification OK).
- Color sensor adjustment improvement.
- Add automatic color readjustment if the ribbon synchronisation failed.

30/10/2014

Firmware version – 1443

- Black printing quality improvement (for color ribbon).
- Set USB to USB 2.0 full speed (USB Certification agreement).
- Design modification of the Technical Card (Internal font change).

26/05/2014

Firmware version – 1426

- Original firmware version.

